



# VESKi

Oreškovićeve 8j, Zagreb | Croatia | [www.veski.hr](http://www.veski.hr)

VIBRATION EXPERT SYSTEMS | CONSULTING | SYSTEM DESIGN


## CoDiS protection and diagnostic system BENEFIT EXAMPLES

**CoDiS** Machine Condition Monitoring  
**Computerized Diagnostic System**



Solutions only

## Monitored values: CoDiS system is configured to detect faults



## Fault detection– List of typical faults on hydro turbine and generator

	Measurement													
	Bearing vibrations	Relative shaft vibrations	Bearing temperatures	Turbine cover vibrations	Air gap	Magnetic field	Stator core vibrations	Stator frame vibrations	Generator temperatures	Process quantities	Cavitation	Electrical quantities	Partial discharge	Hydraulic quantities
<b>VESKi</b> Fault detection and Corresponding measurements														
Mechanical Unbalance	1x	1x												
Electrical unbalance	1x	1x												
Hydraulic unbalance	1x,nx													
Misalignment	1x, 2x	1x, 2x												
Eccentricity of stator and rotor		DC												
Bearing wear														
Stator windings vibrations							100Hz 200Hz	100Hz 200Hz						
Insulation wear														
Rotor shape														
Overheated stator coils														
Phase symmetry														
Bearing stiffness														
Excitation problems														
Load angle detection														
Pressure pulsation														

**Data base:** Data recorded to highlight some typical errors

## Increased stator core vibrations – HPP /Vertical Kaplan/ 2 bearings /45 MW unit.

**Problem**


- High vibrations of stator core
- Vibration maximum reached at certain stator core temperature and then amplitudes reduce as the heating continues
- Temperature where maximum is achieved is becoming lower as the loosenes progrades and after few months reached the 20% of nominal

**Detection**

- Stator core loosened after 15 years, probably due to bad assembly
- Stator core change stiffness with temperature
- Resonance of core is at 100 Hz as the core is loosened

**Objective:**

- Stator core exposure to high vibrations as short as possible



Core vibrations

(upper diagram)

Active and reactive power

(middle diagram)

Stator core and winding temp.

(lower diagram)




## Increased stator core vibrations – HPP /Vertical Kaplan/ 2 bearings /45 MW unit.

### Solution proposal

- Regulation of load level and cooling of stator using vibration feedback in order to cross over critical frequency as fast as possible and get out of resonant area


Load level regulation  
(measured vibration  
feedback)  
significant influence on  
vibration level



Stator cooling off  
- In function of  
measured vibrations  
- Faster heating  
exposure  
time minimized

Increased stator core vibrations – HPP /Vertical Kaplan/ 2 bearings /45 MW unit.

**Permanent solution** - Dedicated stator core permanent monitoring system connected to control system (ASEA ProMaster) - **FIRST CoDiS INSTALLATION – 1993.**



## BENEFITS

- system eliminated critical temperature changes
- generator was operational for following 3 years
- after three years (1996) stator core was changed due to a lightning protection failure


- total investement cost:

- expert measurements cost ~ 35,000 US\$

- monitoring system 1993 costs ~ 40,000US\$

- generated energy **> 350 GWh**  
**> 9.500.000,00 US\$**

2003. – System CoDiS refurbishment









## Quick statistical condition estimation – CoDiS-QSCE

### Estimation of stationary operation conditions

- Selecting representative period of operation (typically 1 – 2 months before and 1 – 2 months after overhaul) – evaluation of results
- Selecting values for analysis, significant for condition estimation (typically vibration Smax, s1n, AirGap minimum etc)
- Determining data filters (real and imaginary power levels, rotational speed, temperature etc.)
- Applying statistical data distribution analysis – histograms
- Performing histogram comparison




Histogram's area, x and y maximum and minimum differences are basics for condition stability estimation


## Quick statistical condition estimation module – CoDiS-QSCE

**Estimation of conditions based on RunDown&StartUp data**

- Behaviour repeatability during RunDown and StartUp analysis
- Selection of data significant for condition evaluation (relative and absolute vibrations – Smax, RMS, s1n amplitudes and phases)
- Data filtering – only data recorded during variable speed are submitted to analysis
- Additional to histograms regression analysis is performed
- Comparison of regression curves for various periods is performed



Smax regression analysis  
(Vibration vs Rotational speed)



Regression curves comparison  
(Vibration vs Rotational speed)



## Quick statistical condition estimation module – CoDiS-QSCE

**CoDiS-QSCE analysis results application**

- applied for quick condition estimation in order to plan overhaul procedures – overhaul reduction if conditions are stable (no changes), further analysis if some fault (changes) are indicated

**HPP 2x108MW**

- Bearing opening on condition change or every 3rd year
- overhaul reduction for ~ 15 days
- overhaul cost reduction ~ 180.000 €
- generated energy ~ 28000MWh

**HPP 2x45 MW**

- Bearing opening on condition change or every 2nd year
- overhaul reduction for ~ 18 days
- overhaul cost reduction ~ 216.000 €
- generated energy ~ 8500 MWh

**HPP 2x35MW**

- Bearing opening on condition change or every 2nd year
- overhaul reduction for ~ 15 days
- overhaul cost reduction ~ 180.000 €
- generated energy > 3000 MWh



## HPP 2x 108 – Shaft alignment

**Problem**


- Increased relative vibration level after overhaul measured by CoDiS system

**Detection**

- irregular shaft centerline
- irregular shaft collar assembly on upper generator combined bearing



Run out compensation analysis



2D and 3D shaft alignment and Run-Out analysis

## HPP 2x 108 – Shaft alignment

**Solution**

Irregular thrust collar assembly repair:

- inserting thin metal plates between thrust collar and collar plate
- checking shaft centerline after each metal plate insertion



**Result**

- Reduced repair cost as OEM demanded to dismount the collar and transport 500km to the factory for repairs

Reduced downtime cost for at least 10-12 days

- 2 days for shaft centerline assembly due to automated procedure for run out detection
- 10 days for transport and repair in the factory

Traditional method  
Measurement gauges



Applied - Measurement using  
CoDiS sensors and modules

**RESULT: Metal plates installed on site, no vibro-dynamical behaviour changes reported for 11 years of unlimited operation.**



## HPP 2 x50 MW, Vertica Kaplan – Turbine cover vibrations


**Problem**

- High vibration of generator (AC) in axial direction and high statical (DC) deflection
- Unstable in operation – vibrations occur suddenly in stationary operation
- New machine was out of operation for 2 months

Initial state – axial displacement of rotor

**Detection**

- Low stiffness of turbine cover



Axial displacement of rotor  
Vs structure

Axial displacement of rotor  
Vs turbine cover

## HPP 2 x50 MW, Vertica Kaplan – Turbine cover vibrations


**Solution**

- Increase the turbine cover stiffness applying the rigid elements to the construction

**Result**

- Stiffness increased  $\sim 2X$
- Deflection reduced by  $\sim 2X$
- No more unstable operation and AC vibrations
- **MACHINE AVAILABLE FOR OPERATION 2 WEEKS AFTER MEASUREMENTS**

After correction– axial displacement of rotor



Axial displacement of rotor  
Vs structure

Axial displacement of rotor  
Vs turbine cover

DC  $\sim 0.9$  mm



# Thank you for your attention!

Oreškovićeve 8j, Zagreb | Croatia | [www.veski.hr](http://www.veski.hr) | [info@veski.hr](mailto:info@veski.hr)

Read our case study – <http://sine.ni.com/cs/app/doc/p/id/cs-10016>